

EXHIBIT 11

OUTbound Norfolk
Southern Branch w
week 281, Experienced
a steering malfunction
causing tug and Barge
to turn to port
and Touchup on Bridge
before it could be
corrected, No Damage
to Barge and No
visible Damage to
Bridge,